

Automatic Temperature Checking Set 1 (ATK1)

This Automatic Temperature Checking set is used to check and adjust the firing and press temperatures in furnaces with automatic calibration programs (e.g. EP 600 and EP 600 Combi).



Delivery forms

Automatic Temperature Checking Set 1	559358
Contact pins	2x
Ceramic base block	1x
Melting samples	5x

ATK 1 Melting Samples

10 melting samples for the Automatic Temperature Checking Set 1.



Delivery forms

ATK1 Melting Samples Refill	10x	559359
-----------------------------	-----	--------

ATK 1 Contact Pins / Ceramic Base Block

10 contact pins and 5 ceramic base blocks for the Automatic Temperature Checking Set 1.



Delivery forms

ATK1 Contact Pins / Ceramic Base Block Refill	10x	559582
Contact pins	10x	
Ceramic base block	5x	