

Temperature Checking Set 2

The temperature checking set is used to check and adjust the temperature in the Programat furnace chamber (for Programat® P200, P300, P310, Programat X1, etc.).



Delivery forms

Temperature Checking Set 2	544903	
Sample holder	2x	
Silver test wires	10x	

Silver Test Wires

Refill package containing 5 silver test wires for the Temperature Checking Set 2.



Delivery forms

Silver Test Wires Refill	5x	545634
--------------------------	----	--------

Automatic Temperature Checking Set "ATK2"

The Automatic Temperature Checking set "ATK2" is used to check and adjust the firing temperatures in furnaces with automatic calibration programs for the ATK2 system (e.g. Programat® P500, P510, P700, P710, CS, CS2, CS3, EP 3000, EP 3010, EP 5000, EP 5010).

The simultaneous double-range calibration is a special feature of the ATK2.



Delivery forms

Automatic Temperature Checking Set "ATK2"	598833	
ATK2 samples	5x	