

Ceramic Sleeves for Metal Pins

The ceramic sleeves can be placed on the metal pins to avoid that metal-free restorations come in contact with the metal pins.



Delivery forms

Ceramic Sleeves for Metal Pins Refill		666068
Ceramic Sleeves		10x

Automatic Temperature Checking Set "ATK 2"

The automatic temperature checking set "ATK 2" is used to check and adjust the firing temperatures in furnaces with automatic calibration programs for the ATK2 system (e.g. Programat® CS2). The simultaneous double-range calibration is a special feature of the ATK2.



Delivery forms

Automatic Temperature Checking Set "ATK 2"		598833
ATK 2 Samples		5x

Firing Tongs

These firing tongs are used to place objects in the firing chamber. High precision and excellent material quality are the special features of these tongs.



Delivery forms

Firing Tongs	1x	530665
---------------------	-----------	---------------